

# **IMGA 740**

**IMPAC-Pyrometer** 



# Operation Manual · Betriebsanleitung





# **Contents**

1	Bas	ic Information	1
	1.1	Notes for the User Manual	1
	1.2	Document Structure and Symbols	1
	1.3	Purpose	1
	1.4	Intended Use	1
	1.5	Warranty and Liability	2
2	Safe	etv	3
	2.1	•	
	2.2	General Safety Notes	
3	Sco	pe of Delivery / Accessories	4
	3.1	Scope of Delivery	
	3.2	Device models	
	3.3	Accessories	4
4	Tecl	hnical Data	6
	4.1	Properties	6
	4.2	Measurement ranges	7
	4.3	Drawing pyrometer	7
5	Tecl	hnical Description	8
	5.1	System Design / Principle of Operation	8
	5.2	Optics	8
		5.2.1 Vario optics	8
		5.2.2 Macro optics	8
		5.2.3 Setting the vario optics	9
	5.3	Operating elements and cable connections	10
	5.4	Operating and display elements bench unit	10
	5.5	Operation with bench unit	10
	5.6	Connection for 12-pole connecting cable	
	5.7	Cooling connection	
	5.8	Mounting	
	5.9	Emissivity	12
6	Star	rting Up	13
	6.1	Installation Site Requirements	13
		6.1.1 Climatic conditions	13
		6.1.2 Requirements at the place of use	13
	6.2	Installation	14
		6.2.1 Fix and connect the pyrometer	14
		6.2.2 Align pyrometer	15
7	Troi	ubleshooting	16



8	Transport and Storage						
	8.1	Transport of the Pyrometer	17				
	8.2	Storage of the Pyrometer	17				
9	Mair	ntenance and Care	18				
	9.1	General information	18				
	9.2	Cleaning the Optics	18				
10	Taki	ing out of service, Disposal	19				
	10.1	Taking out of service	19				
	10.2	Pisposal	19				



# 1 Basic Information

#### 1.1 Notes for the User Manual

This user manual describes the structure of the IMPAC® IMGA 740 infrared pyrometer for non-contact temperature measurement and gives the operators all the necessary information related to installation, operation, de-installation along with information related to maintenance and repairs of the pyrometer. When malfunctions occur, the user manual provides suggestions for their potential causes and their repair.

This user manual is intended for qualified service and maintenance personnel with appropriate technical expertise including a basic knowledge of temperature measuring technology.

Before you use the pyrometer for temperature measurement, you must have read and understood these operating instructions! Keep the manual so that it is available at all times.

Take into account all the requirements given in this user manual. This is a precondition for:

- The correct and professional use of the pyrometer
- · Proper maintenance, cleaning and care of the pyrometer
- · Prevention of risks and strict observance of the essential technical safety regulations

# 1.2 Document Structure and Symbols

**Operating instructions** to be performed in sequence are numbered in chronological order. They are grouped together in operational units and accompanied by the corresponding results.

Listings without a sequential order are presented as bullet points and items in sub-lists are preceded by dashes.

**Safety precautions** are shown with pictograms and key words. They provide information about the type, source and consequences of the hazard, and safety precautions. The meanings of the pictograms and key words are explained in Safety (section 2) at page 3.

# 1.3 Purpose

The IMPAC IMGA 740 pyrometer is particularly intended for the non-contact measurement of surface temperatures on metal, ceramic, plastics and is specially designed for industrial applications as well as applications in the area of research and development.

The IMPAC IMGA 740 also enables you to solve high speed applications in laser areas by using laser rejection filters and challenging temperature measurement on silicon or tungsten.

## 1.4 Intended Use

The IMPAC IMGA 740 pyrometer is to be used exclusively for the non-contact measurement of surface temperatures of the materials specified in Purpose (section 1.3) at page 1. Any applications beyond that area are not allowed! Any damage resulting from this is the sole responsibility of the operator.

Proper use of the device also includes:

- The observance of the requirements of these operating instructions for transport and storage, assembly, operation and care of the pyrometer
- The observance of the power requirements specified in Technical Data (section 4) at page 6 and the operating and environmental conditions
- The compliance with the legal accident prevention and environmental regulations

Among applications/conditions for which the pyrometer is not intended for use are in particular:

· The use of the pyrometer within medical areas



- · The use of the pyrometer in the food industry
- The use of the pyrometer in areas where there is danger of explosion
- The use of the pyrometer outside of the operating and environmental conditions specified in Technical Data (section 4) at page 6

# 1.5 Warranty and Liability

LumaSense Technologies® offers a 2 year warranty for the device starting from the date of invoice. The warranty covers manufacturing defects. Then the device will be repaired free of charge, however freight charges are the responsibility of the respective sender.

LumaSense Technologies reserves the right to exchange the equipment or parts of the instrument instead of a repair. After a repair, LumaSense Technologies offers a warranty of 12 months on all repaired and/ or exchanged instrument components.

Deviations from the proper use described in this user manual will result in restricted warranty and liability or the loss in case of damage. Damage to wearing parts (e.g. fuses) is excluded from the guarantee.

Warranty and liability claims for personal injuries and/or material damage are excluded if this or these result from one or more of the following causes:

- · Improper use of the device
- · Inappropriate operation and servicing of the device
- · Unauthorized modifications to the device without prior consultation with LumaSense Technologies
- · Rough, mechanical actions or deliberate destruction of the device
- · Connection error (overvoltage)
- Frost damage by not observing the permitted environmental conditions and/or by inappropriate storage
- Malfunctions that are caused by non-conformance to this user manual



# 2 Safety

## 2.1 Used symbols and key words

The following symbols and key words are used in the user manual to indicate hazards and instructions. Safety precautions always appear before an action.



#### DANGER:

Indicates a potentially dangerous situation. Failure to abide may result in light or minor injury and damage.



#### **CAUTION:**

Indicates a potentially damaging situation. Failure to abide may result in damage to the product or to anything near the product.



#### **IMPORTANT:**

Indicates useful tips and other specifically useful information that allow any dangerous or damaging situations to be avoided.



#### REFERENCE TO ENVIRONMENTAL PROTECTION:

Important instructions for protecting the environment.

# 2.2 General Safety Notes

The IMPAC IMGA 740 pyrometer has been built in accordance with the currently valid standards of the technology and the recognized safety regulations and ensures the highest safety level.

The fundamental safety and occupational safety requirements of applicable laws, standards, and guidelines have been taken into account in the pyrometer design. The safety of the pyrometer is confirmed by the declaration of conformity and the CE mark.

All information related to safety is with reference to the regulations of the European Union currently in force. In other countries, applicable laws, national directives and safety regulations have to be met.

Apart from the safety instructions given in these operating instructions, you should also take into account the generally valid regulations for accident prevention and environmental protection as well as the regulations of the respective professional associations and strictly comply with them.

Note the general safety instructions:

- Commissioning of the pyrometer may only be carried out by persons qualified to do so, taking the safety instructions into account.
- · Pay attention to the installation site requirements and notes for commissioning.
- Only use the original cables provided as accessories for the connection of the pyrometer. Other cables, especially cables manufactured by yourself, are not permitted.
- Before start-up, carry out a visual inspection for damage to the components of the pyrometer(housing, optics, cable and pipes). Never operate the pyrometer with damaged components.



# 3 Scope of Delivery / Accessories

# 3.1 Scope of Delivery

The scope of delivery of the pyrometer includes:

- · High speed infrared pyrometer
- Retaining bolt  $\varnothing$  14.9 mm, length 100 mm, thread M12
- Water cooling connection
- Bench unit IMPAC KBU 1600-USB with digital display, power supply, USB-interface, adjustable emissivity, trigger input
- USB cable
- · BNC cable
- · Connecting cable for pyrometer
- · Power supply cable
- · CD-ROM with evaluation software
- · Inspection sheet
- · User manual



#### **IMPORTANT:**

Requirements for PC are CPU with min. 1,5 GHz and USB 2.0 interface

### 3.2 Device models

ArtNo.	Description	Configuration	Measuring range
47400-09990	IMGA 740	Current output 0 20 mA or 4 20 mA	350 3,500
47400-01990	_	Vario optics or macro optics	600 1,600
47400-02990	_		800 2,300
47401-01990	_		300 1,400
47401-02990	_		500 2,500
47402-01990			160 1,000
47402-02990	_		300 2,300

# 3.3 Accessories

## **Connecting cable**

ArtNo.	Description
30007-14050	Connecting cable, connector, straight, 12-pol., 5.0 m
30007-14100	Connecting cable, connector, straight, 12-pol., 10.0 m
30007-14150	Connecting cable, connector, straight, 12-pol., 15.0 m
30007-14200	Connecting cable, connector, straight, 12-pol., 20.0 m
30007-15050	Connecting cable, connector, straight, 12-pol., jack 12-pol., 5.0 m
30007-15100	Connecting cable, connector, straight, 12-pol., jack 12-pol., 10.0 m
30007-15150	Connecting cable, connector, straight, 12-pol., jack 12-pol., 15.0 m
30007-15200	Connecting cable, connector, straight, 12-pol., jack 12-pol., 20.0 m



## **BNC-connecting cable**

ArtNo.	Description
30007-91040	BNC-connecting cable, 4.0 m
30007-91075	BNC-connecting cable, 7.5 m
30007-91100	BNC-connecting cable, 10.0 m
30007-91150 BNC-connecting cable, 15.0 m	
30007-91200 BNC-connecting cable, 20.0 m	
30007-91900	Extension BNC-connecting cable, per meter

#### **Device mounting**

ArtNo.	Description			
30002-10010	Ball and socket mounting screw mounted			
30002-10020	Ball and socket mounting clamp mounted			

### **Accessories for optics**

ArtNo.	Description
30002-20010	Vario optic
30002-20030	Vario optic with air purge unit
30002-20020	Macro optic
30002-20040	Vario optic with protective glass
30003-03410	Laser rejection filter 1064 nm

## Scanner and Maximum value storage

ArtNo.	Description
30002-30020	Optical scanner SC 1 with screwed flange
30002-30030	Maximum value storage (only in combination with optical scanner SC 1)
30002-30060	Protective glass Borofloat 58 x 34 mm

#### **Order information**

Please send your orders for accessories to the following address. When ordering, please quote the type, the name of the accessory part, and the quantity.

## Service address

LumaSense Technologies, Inc.

Phone: +49 (0)69 / 9 73 73 - 0

Kleyerstr. 90

Fax: +49 (0)69 / 9 73 73 - 167

D-60326 Frankfurt/Main

E-Mail: eusupport@lumasenseinc.com

Germany

Internet: www.lumasenseinc.com

5



# **Technical Data**

# **Properties**

Measurement outlet analog	0 20 mA or 4 20 mA, maximum burden 500 $\Omega$		
Measurement outlet digital	USB-connection to PC		
Accuracy	0.75 % of measured value (at 25 °C , $\varepsilon$ = 1)		
Reproducibility	< 0.3 % of measured value (at 25 °C, $\varepsilon$ = 1)		
Response time t <sub>95</sub>	10 μs		
Emissivity $\varepsilon$	Adjustable from 0.11 (with bench unit and software)		
Optic	Vario optics or macro optics		
Aiming device	LED pilot light or through lens sighting		
Operating temperature	0 +40 0 +80 °C with water cooling		
Storage temperature	-20 +70 ℃		
Water cooling connection	2 Tube screw connector 0.25"		
Cooling water	Temperature 1035 ℃, pressure maximum 6 bar, flow rate at least 1 l/min		
Relative humidity	Non condensing conditions		
Power supply	230 V AC, 50 60 Hz (115 240 V possible)		
Degree of protection pyrometer	IP 54 according to DIN 40 050		
Degree of protection bench unit	IP 20 according to DIN 40 050		
Test base	EN 55 011 : 1998, limit class A		
CE marking	According to EU regulations		
Dimensions pyrometer	170 x 70 x 70 mm (LxWxH) Length with maximum extension of optics 320 mm		
Dimensions bench unit	335 (365) x 310 (310) x 155 (260) mm (LxWxH) value in brakes incl. relay		

# Vario optics

D <sup>a</sup> in mm	450	600	800	1,000	1,200	1,400	1,600	1,800	2,000	2,500	3,000	
M <sup>b</sup> in mm	2.5	4.0	6.0	8.0	10.5	11.5	13.0	14.0	15.0	20.0	28.0	

<sup>&</sup>lt;sup>a</sup>Distance from optics front edge

# **Macro optics**

Spectal range	0.85 $\dots$ 1.05 $\mu$ m, 1.58 $\dots$ 1.80 $\mu$ m	1.58 $\dots$ 2.20 $\mu$ m, 2.00 $\dots$ 2.20 $\mu$ m
D <sup>a</sup> in mm	144	140
L <sup>b</sup> in mm	144	150
M <sup>c</sup> in mm	0.7	1.0

<sup>&</sup>lt;sup>a</sup>Distance from optics front edge

<sup>&</sup>lt;sup>b</sup>Measuring field diameter

<sup>&</sup>lt;sup>b</sup>Fix length tube extraction <sup>c</sup>Measuring field diameter



# 4.2 Measurement ranges

Туре	Meas. range	Spectral range	
IMGA 740	600 1,600 °C	$0.85\dots1.05~\mu{ m m}$	MB 16 Pilot light has to switched off during the measurement, as this may falsify the measurement result.
IMGA 740	800 …2,300 ℃	$0.85\dots1.05~\mu{ m m}$	MB 23 Pilot light has to switched off during the measurement, as this may falsify the measurement result.
IMGA 740	300 1,400 ℃	1.58 $\dots$ 1.80 $\mu$ m	MB 14
IMGA 740	5002,500 ℃	1.58 $\dots$ 1.80 $\mu$ m	MB 25
IMGA 740	1601,000 ℃	1.58 $\dots$ 2.20 $\mu$ m	MB 10
IMGA 740	3002,300 ℃	2.00 $\dots$ 2.20 $\mu$ m	MB 23
IMGA 740	350 3,500 ℃	2.00 2.20 μm	MB 35

# 4.3 Drawing pyrometer




Figure 1: Drawing pyrometer



# 5 Technical Description

# 5.1 System Design / Principle of Operation

Figure 2 shows the basic structure of the pyrometer. The basic parts of a pyrometer are the lens, aperture, filter detector, and the signal processing unit. The infrared radiation coming in from the object to be measured is gathered by the lens. The aperture blocks unwanted rays at the edges. The filter permits only the desired spectral range to enter. The rays then pass through to the detector which transforms the infrared radiation into electric signals. These signals are then linearised in the signal processing unit and changed into a standard output signal which can then be read in the display, and be used for process control.

The operating elements as well as the connections / interfaces are located at the back of the pyrometer (see Operating elements and cable connections (section 5.3) at page 10) and at the bench unit (see Operating and display elements bench unit (section 5.4) at page 10).

On the bottom of the pyrometer are the coolant connections and a threaded hole for mounting the pyrometer.




Figure 2: Structure of the pyrometer

### 5.2 Optics

#### 5.2.1 Vario optics

The vario optics can be adjusted to the required measuring distance and allows small measuring fields for various distances to the object being measured. The measurement object can be at an arbitrary distance, but must be at least as large as the measuring field at that distance (see Setting the vario optics (section 5.2.3) at page 9).




Figure 3: Vario optics

#### 5.2.2 Macro optics

The macro optics is a fixed optics for very small measuring fields, i.e. a certain measuring field diameter is given for a certain measuring distance.






Figure 4: Macro optics

Spectal range 0.85 ... 1.05  $\mu$ m, 1.58 ... 1.80  $\mu$ m 1.58 ... 2.20  $\mu$ m, 2.00 ... 2.20  $\mu$ m

D <sup>a</sup> in mm	144	140
L <sup>b</sup> in mm	144	150
M <sup>c</sup> in mm	0.7	1.0

<sup>&</sup>lt;sup>a</sup>Distance from optics front edge

<sup>&</sup>lt;sup>c</sup>Measuring field diameter



#### **IMPORTANT:**

The macro tube cannot be adjusted. The distances mentioned must be respected absolutely in order to ensure the small measuring field.

#### 5.2.3 Setting the vario optics

Adjust the vario optic as follows:

- 1. If necessary switch on the pilot light.
- 2. Loosen the ring nut by turning it in a counter-clockwise direction.
- 3. Move the vario optic forwards and/or backwards, in order to adjust the pyrometer to the required measuring distance.

Note: The size of the pilot light is identical to the size of the measuring field. The measuring field may not be larger than the object to be measured at the adjusted distance!

- 4. After adjusting the measuring distance, lock the annular nut by turning it in a clockwise direction
- √ The vario optic is thus adjusted to the required measuring distance.




Figure 5: Setting vario optics

D <sup>a</sup> in mm	450	600	800	1,000	1,200	1,400	1,600	1,800	2,000	2,500	3,000	
M <sup>b</sup> in mm	2.5	4.0	6.0	8.0	10.5	11.5	13.0	14.0	15.0	20.0	28.0	

<sup>&</sup>lt;sup>a</sup>Distance from optics front edge


 $<sup>^</sup>b {\sf Fix}$  length tube extraction

<sup>&</sup>lt;sup>b</sup>Measuring field diameter



# 5.3 Operating elements and cable connections

The operating elements and cable connections are located on the rear side of the device.



Element	Meaning
Push button for pilot light (Alternative: Instead through lens sighting)	Switch on/ off the pilot light
BNC output	Measurement output 0 10 V
12-pin plug connection	Power supply connection, current output, digital connection to the bench unit

Figure 6: Rear side pyrometer

# 5.4 Operating and display elements bench unit

Controls and indicators are located on the front and rear side of the bench unit. For the meaning of individual elements refer to legend Figure 7 and Figure 8, for operation of the bench unit see Operation with bench unit (section 5.5) at page 10.




Figure 7: Front view KBU 1600-USB




Figure 8: Rear view KBU 1600-USB

Element	Meaning
1 Display	Shows temperature
2 Display	Shows emissivity
3 LED red	Shows USB status
4 Push-button	Emissivity up
5 Push-button	Emissivity down
6 BNC Input	Trigger-Input
7 LED green	Trigger-Input Status LED
8 Push-button	Toggle between ℃ and °F

Element	Meaning			
1 12-pin plug con-	Connection to the py-			
nection	rometer			
2 USB connector	Connection to the PC			
3 BNC Input	Connection to the py-			
	rometer			
4 Two wire output	0 / 4 20 mA output			
5 Power supply	Connector with fuse and switch			

# 5.5 Operation with bench unit

After starting up the measuring station the actual temperature and adjusted emissivity will be displayed (see Figure 7).



The temperature unit can be chosen by pushing the button " $^{\circ}$ C /  $^{\circ}$ F". Possible units are degree centigrade ( $^{\circ}$ C) or degree Fahrenheit ( $^{\circ}$ F). This adjustment will be taken over by the software automatically.

The actual measured temperature is displayed. If this display is blinking after starting up, the pyrometer is not connected correctly.

The emissivity can be adjusted with the up and down buttons from 10 . . . 100 %. The emissivity will be displayed with 3 digits. This adjustment will be taken over by the software automatically.

The red LED at the front of the bench unit shows the status of USB connection. The measuring station is connected to PC and drivers are installed correctly if the LED glows.

The green LED at the front side of the bench unit glows, if TTL H-Level is connected to trigger input.



#### **IMPORTANT:**

If a measurement is started via software, operation with bench unit is blocked and display will not be updated!

## 5.6 Connection for 12-pole connecting cable

The plug for the 12-pole cable is at the rear side of the pyrometer and also of the bench unit. The contacts of the 12-pole plug arranged as follows:




Figure 9: Connection 12-pole ca-
ble

Contact	core	meaning
K	White	+24 V supply voltage
Α	Brown	0 V supply voltage
L	Green	Analog output 0 / 4 20 mA +
В	Yellow	Analog output 0 / 4 20 mA -
M	Orange	Screen
G	Red	DGND (ground for interface)
F	Black	RxD (RS 232)
С	Violet	TxD (RS 232)
Н	Grey	not connected
J	Pink	not connected
D	Grey / pink	not connected
E	Red / blue	not connected

Maaning

cable

### 5.7 Cooling connection

At ambient temperatures of more than 40 °C the pyrometer must be operated with the associated cooling! The two connections for the connection of a cooling circuit are located under the instrument (see Drawing pyrometer (Figure 1) at page 7).

The following should be taken into account when connecting a cooling circuit:

- Flow rate at least 1 l/min
- · Pressure maximum 6 bar
- Coolant temperature 10 ...35 °C

Cold tap water is usually sufficient for cooling. It should not be so strongly cooled that condensation develops on the instrument. Take into account the environmental conditions (air temperature and humidity) with respect to the cooling.



## 5.8 Mounting

To mount the pyrometer, a threaded drilling M12 is located on the underside of the unit. The pyrometer can be attached to different mountings.

We recommend to use the retaining bolt supplied with the pyrometer or the optional available ball and socket mounting support with clamp or thread. This mounting plate ensures secure assembly of the pyrometer (for order data see Accessories (section 3.3) at page 4).

# 5.9 Emissivity

The emissivity is the relationship between infrared energy radiated from an object and the radiation energy of a perfect emitter (black emitter) at the same temperature and the same spectral range.

The emissivity is material-dependent and of a considerable size in order to be able to determine the temperature of an object accurately without contact. The emissivity of the object being measured must therefore be known and be adjusted at the pyrometer.

Typical emissivities for various materials are available on our homepage at www.lumasenseinc.com or in relevant literature.

The instrument is calibrated at black body radiation ( $\varepsilon$  = 1,00). Real objects have an emissivity less than  $\varepsilon$  = 1.00. This difference can be adjusted with changing the emissivity value from the pyrometer.

#### How to find out correct emissivity:

- 1. Measure the real temperature of measuring object with a contact thermometer e.g. thermocouple or resistance probes.
- 2. Align the pyrometer at the measuring object and adjust the emissivity until both devices (pyrometer and contact thermometer) show the same temperature value.
- ✓ After adjusting the emissivity factor through a correlation measurement you can now measure temperatures for the calibrated temperature range at an accuracy mentioned in the technical data.



#### IMPORTANT:

Please pay attention if you take over table values of emissivity to give the value of emissivity factor at a certain wave length. Adjusting emissivity following table values is not as exactly as adjusting following a comparing measurement.



# 6 Starting Up

## 6.1 Installation Site Requirements



#### **CAUTION:**

Measurement errors and damage to the pyrometer through

- · Ambient temperatures too high
- Strong contamination of the optics due to dust, smoke, steam or other causes like air pollution
- · Electromagnetic interference sources

You must take into account the following climatic conditions and the requirements of the place of use of the pyrometer!

#### 6.1.1 Climatic conditions

The following requirements must be fulfilled with respect to the climatic conditions at the place of use of the pyrometer:

- Temperature range 0 °C ... +40 °C (up to +80 °C with connected cooling)
- · Maximum air humidity: 60 % at room temperature
- · Atmosphere free of dust, corrosive vapours, and fume gases

#### 6.1.2 Requirements at the place of use

Take into account the following requirements at the place of use of the pyrometer:

- Take care with the choice of the place of use and take into account the ergonomic and the legal guidelines
  for industrial safety in order to ensure safe operation of the pyrometer.
- Set up the pyrometer on a firm, stable base. The base must be free from concussion and vibration.
   Note:

We recommend using the rail mounting plate available as an accessory for the attachment of the pyrometer as well as a clamping attachment (see Accessories (section 3.3) at page 4).

- Do not expose the system to direct sunlight or radiation from heating (e.g. radiators).
- Do not set the pyrometer near strong electromagnetic fields or near electromagnetic interference sources.
- Make sure that the pilot light falls unhindered on the object being measured and that there is nothing in the path of the rays.

Take into account the following requirements at the place of use of the bench unit:

- Place the bench unit on a preferably flat, big enough surface.
- The maximum distance from the bench unit to the PC is 5 m due to maximum USB cable length specifications.
- The distance between pyrometer and bench unit should not exceed 20 metres.



#### 6.2 Installation

#### 6.2.1 Fix and connect the pyrometer



#### DANGER:

There is danger of injury and possible equipment damage by connection of cables under power! Never connect cables under power! Make sure that the voltage supply is switched off before connection of the cables to the pyrometer!



#### **IMPORTANT:**

Operation of the pyrometer about ambient temperatures of more than 40 °C is **only permitted with water cooling!** Connect the pyrometer to a suitable cooling circuit with ordinary tap water! The use of coolants is permitted only with the agreement of the manufacturer!

The temperature of the cooling water must lie between 10 and 35 °C. Condensation build-up due to the low temperature of the cooling water is to be avoided.

#### Install the pyrometer as follows:

- 1. Make sure that the power supply switch on the back of the bench unit is switched "OFF" or shows "0" before plugging in all connecting cables.
- 2. Mount the pyrometer with the help of the retaining bolt and taking into account the conditions specified in Installation Site Requirements (section 6.1) at page 13 for the intended place of use. Note: Do not exceed the 12 mm screw-in depth from the pyrometer.
- 3. Connect, if necessary (only in case of ambient temperatures more than 40 °C) the water cooling.
- 4. Connect the pyrometer and bench unit with the 12-pin cable (see Figure 6 and Figure 8).
- 5. Connect the pyrometer and bench unit with the BNC cable (see Figure 6 and Figure 8).
- 6. Double check stable set up of the pyrometer.
- 7. Connect the bench unit with the provided power supply cable with a normal 230 V power outlet. Depending on the voltage of your country an optional power supply of 115 V is also possible (see Figure 8).
- 8. The USB cable will be connected between the socket on the back of the bench unit (see Figure 8) and a not used USB interface on your PC (max. cable length 5 m!).
- $\checkmark$  The pyrometer and bench unit is ready for use and can be switched on. (Before that install the software)



#### **IMPORTANT:**

Suitable adapters for connection to power outlets of your country are not included in delivery scope!

# Optional connectable cables:

- Measuring cables for 0 / 4 ... 20 mA output on the back of the bench unit (see Figure 8).
- BNC cable for trigger input on the front of the bench unit (see Figure 7).



#### IMPORTANT:

These cables are not included in delivery scope!



#### 6.2.2 Align pyrometer

The pyrometer is equipped with an LED pilot light for accurate alignment of the sensor with the object to be measured. Align the pyrometer with the object to be measured as follows:

- 1. Switch on the supply voltage to the pyrometer.
- 2. Allow a starting time of approx. 5 minutes for thermo-stabilization. Than the pyrometer has stabilized and is ready to work with the given accuracy.
- 3. Switch on the pilot light. Make sure that there is nothing in the path of rays.
- 4. When the measuring distance of the used optics can be changed, set the optic regarding to the needed measuring distance. The resulting measuring field diameter must not be larger than the object to be measured (see Setting the vario optics (section 5.2.3) at page 9). Align the optics according to the measuring distance on the measuring object, using the pilot light. Make sure that there are no objects in the path of rays.
- √ The pyrometer is thus aligned and ready for temperature measurement.



# 7 Troubleshooting



#### **DANGER:**

There is a danger of injury and possible equipment damage through incorrect power supply! Let problems relating to an incorrect power supply be eliminated by an electrical specialist! Do not carry out arbitrary work on the electrical components of the pyrometer!

Only eliminate such problems yourself when their causes obviously relate to incorrect power supply, undercooling or contamination of the lens.

Do not undertake any interventions into the pyrometer. If problems arise which do not relate to the causes mentioned above, inform the service staff of the LumaSense Technologies.(for contact data see (section 2.2) at page 5)

Fault	Cause	Solution
Pyrometer does	Power supply faulty or in-	Check the power supply
not provide any measured values	terrupted	Check plugs and connections
		Inspect cable
Software don't con- nect with the bench unit	Driver not (right) installed or cable connection not right	Reinstall the Driver, inspect cable
If the pyrometer supplies inaccurate	Dirty optics or condensation on the lens	Clean optics (see Cleaning the Optics (section 9.2) at page 18)
measured values or measured values which lie outside the range to be expected	Water cooling (if available) too strong / weak or air humidity too high	Check water cooling (see Cooling connection (section 5.7) at page 11)



# 8 Transport and Storage

# 8.1 Transport of the Pyrometer



#### **CAUTION:**

Environmental factors, impacts and the formation of water condensation may damage some components!

When transporting the pyrometer, take suitable measures to protect all components from environmental factors, impacts and the formation of water condensation! Temporary storage of the pyrometer in the open air is not permitted!

Look at Taking out of service (section 10.1) at page 19 how to dismantle the pyrometer.

It is advisable to use the original packaging for the shipping of the pyrometer. If the original packaging is no longer available, the pyrometer should be shipped in a cardboard box with shock-absorbing PE material.

When transporting the pyrometer observe the following instructions:

- Take great care when transporting the pyrometer to avoid damage through the effect of force, or careless loading or unloading.
- Avoid jerks, vibrations and the formation of condensed water due to severe temperature deviations while transporting.
- In the case of overseas shipping, a suitable desiccator (e.g. silica gel) should be inserted and the pyrometer should be sealed together with the desiccator in a protective plastic sheet.
- If the pyrometer is not immediately installed after delivery and put into operation, then it should be carefully stored in a location protected against dust and humidity (Storage of the Pyrometer (section 8.2) at page 17).
- √ The pyrometer is thus ready to be shipped.

### 8.2 Storage of the Pyrometer



#### **CAUTION:**

Environmental factors, impacts and the formation of water condensation may damage some components!

Store the pyrometer only in dry areas without large variations in temperature! The atmosphere should be free of dust and corrosive vapors!

Store the pyrometer appropriately in the original packaging. Put a suitable desiccant inside the packing (e.g. silica-gel) to prevent damage by moisture. Protect the pyrometer against dust through suitable measures.

The following climatic conditions are required in the storage room of the pyrometer:

- Temperature range -20 °C ...+70 °C
- Maximum air humidity to 70 %
- · Atmosphere free of dust and corrosive vapors



# 9 Maintenance and Care

#### 9.1 General information



#### **CAUTION:**

Humidity can lead to the destruction of the electrical and electronic components!

Do not use any liquids for cleaning the pyrometer or cleaning the immediate of the pyrometer!



#### **IMPORTANT:**

The servicing period depends particularly on the operating and environmental conditions and is therefore to be specified by the operator!

The pyrometer is largely maintenance-free. Its function depends, however considerably on the condition of the optics. The optics must therefore be checked and if necessary cleaned at regular intervals according to the operating and environmental conditions (see Cleaning the Optics (section 9.2) at page 18). This is necessary in particular if the measured temperature levels do not lie in the expected range.

In the case of excessive contamination or scratches of the optics, please contact the technical customer service (contact address see (section 2.2) at page 5).

Check the cables and the housing at regular intervals for damage and a firm seating.

## 9.2 Cleaning the Optics

Clean the lens with a soft cloth or cotton pad and with white spirits. The optics is thus cleaned and the pyrometer is again ready for use.



# 10 Taking out of service, Disposal

## 10.1 Taking out of service



#### DANGER:

Removing electrically live cables risks injury and damage to equipment.

Never remove electrically live connecting cables. Before removing a cable, ensure that the power supply has been switched off.

Take the pyrometer out of operation as follows:

- 1. Switch off the power supply to the pyrometer / bench unit.
- 2. Remove the cables at the rear side of the pyrometer.
- 3. When used the cooling water supply:
  - · Switch off the cooling water supply.
  - Remove the connections of the cooling system and empty the remaining cooling water from the cooling ducts of the pyrometer.
- 4. Dismantle the pyrometer from the mounting plate.
- 5. If necessary bring the optics in and tighten the annular nut.
- 6. Remove the last cables from the bench unit.
- $\checkmark$  The pyrometer is thus out of operation.

# 10.2 Disposal



For disposal, you can return the pyrometer to LumaSense Technologies (for address see (section 2.2) at page 5, WEEE-Reg.-Nr. DE 97534413). For this you should pack the pyrometer appropriately in the original packaging or use a cardboard carton with shock absorbing PE material.



#### REFERENCE TO ENVIRONMENTAL PROTECTION:

Do not dispose of the pyrometer with domestic refuse!

# **LumaSense Technologies**

**Temperature and Gas Sensing Solutions** 

# 上海麦兴仪器设备有限公司

Shanghai MaxSun Industrial Co., Ltd.

地址:上海市浦东新区张杨路188号汤臣中心A座

邮编:200122

电话:(86 21) 5888 6718 / 133 8186 8102

传真:(86 21) 5888 7876 邮箱:mx@imaxsun.com

# 麦兴(中国)有限公司

MaxSun (China) Limited.

地址:香港湾仔告士打道151号国卫中心11楼

电话:(852) 2836 8361 传真:(852) 3011 5863 邮箱:mx@imaxsun.com